

## **IED Report**

REL TO

CLASSIFICATION: SECRET RELEASABILITY: USA,

**ACGU** 

**BLAST-**

TRACKING NUMBER: 20111114092038SNA0132 DATE DISCOVERED: 2011-Nov14 09:20

647260

CALL SIGN: Jester 1-3

REPORTING UNIT:

Reported

PRIMARY SAFE SECONDARY SAFE Not

AREA(MGRS): 38SNA0150146959 AREA(MGRS): Reported

Not

MGRS: 38SNA0132647260 EVENT TYPE: Reported

COALITION:

KIA: WIA:

0 0

CIVILIAN:

KIA: WIA:

0

**HOST NATION:** 

KIA: WIA:

0 0

**Equipment Used** 

Equipment Used 1

EQUIPMENT USED TYPE: Crew EQUIPMENT USED NAME: Not Reported

Team Data

SERVICE AFFILIATION: USA

EOD NOTIFICATION: 2011-Nov-14 09:25

EOD FOB DEPARTURE: 2011-Nov-14 09:50 EOD SCENE ARRIVAL: 2011-Nov-14 10:25

EOD SCENE EOD MISSION

DEPARTURE: 2011-Nov-14 11:31 COMPLETE: 2011-Nov-14 12:10

14-November-11 Page 1of 3

USCENTCOM FOIA 17-0112 076 08/08/2018



Site Data

SITE MARKED: No

MARKING DETAILS: Not Reported

CIVILIAN ACTIVITY: Normal Activity

REFERENCE POINT: Unknown

AIMING POINT DETAILS: Not Reported

FIRING POINT DETAILS: Not Reported

FIRING POINT MGRS: Not Reported

LIGHT CONDITIONS: Daytime

WEATHER: Not Reported

ROUTE PATROL: Not Reported

LAST TIME ROUTE

CLEARED: Not Reported

ANALYSIS: Not Reported

Devices

Device 1

DEVICE DESCRIPTION: TL assesses the EFP to be dual array, utilizing

approximately 10 inch steel plates with approximately

40lbs of UBE.

MGRS: Not Reported

PLACEMENT: Concealed - LOCATION:

Debris/Rubble Right Side

Pile

CONTAINER: CONTAINER SUB-TYPE: Not

Reported

Road -

HOW DEVICE WAS FOUND: WHO FOUND DEVICE: Not Detonation

Applicable

077 08/08/2018

ACTION TAKEN: Post Blast

**EXPLOSIVE EFFECT:** Blast

14-November-11 Page 2of 3

MAIN CHARGE CONFIGURATION: Directional-EFP

CASUALTIES: No SUICIDE DEVICE: No FIRST RESPONDER TARGETED: No

POST BLAST: Yes PARTIAL BUILD: No

**Targets** 

TARGET PRECEDENCE: Primary AFFILIATION: Coalition

COUNTRY: USA - UNITED TARGET TYPE: Military

STATES

DETAILS: Patrol INTENDED EFFECT: Anti-Armor

**DESCRIPTION:** 4 Caiman Patrol.

Initiators

**Not Reported** 

Munitions

Not Reported

14-November-11 Page 3 of 3

USCENTCOM FOIA 17-0112 078 08/08/2018



#### \*\*\*\*SIGACT CLOSED\*\*\*\*

#### **SIGACT Report**

TITLE: (EXPLOSIVE HAZARD) IED EXPLOSION RPT (Directional IED) 2/B/2-8

CAV, 1-1 CAV IVO (ROUTE MSR TAMPA): 0 INJ/DAM

TRACKING NUMBER: 20111114092038SNA0132647260

REPORT PRECEDENCE: Routine

CLASSIFICATION: SECRET RELEASABILITY: REL TO USA, FVEY

REPORTING UNIT NAME: USD-C G3 SIGACT

MANAGER

REPORT SOURCE:

Coalition

#### **SPOT Section**

UNIT NAME INVOLVED: 2/B/2-8 CAV, 1-1 CALL SIGN: Not Reported

CAV

TYPE OF INVOLVED UNIT: CF INVOLVED UNIT ACTIVITY: Other

INCIDENT REPORTED BY: Coalition Forces BATTLESPACE LEAD: Coalition

TIP REPORTED BY: Not Reported DTG CREATED (LOCAL): 2011-11-14

10:57:13

DTG OF INCIDENT (LOCAL): 2011-11-14 DTG UPDATED (LOCAL): 2011-11-15

09:20:00 16:34:12

Location

MGRS: 38SNA0132647260 ROUTE: MSR TAMPA

**Events** 

EVENT TYPE: Explosive Hazard MODES OF ATTACK: Directional IED

15-November-11 Page 1of 6
-SECRET//REL TO USA, FVEY

USCENTCOM FOIA 17-0112

079 08/08/2018

#### SECRET//REL TO USA, FVEY

**EVENT CATEGORY:** IED Explosion PRIMARY INTENDED OUTCOME: Anti-Personnel SUICIDE?: No EFFECTIVE HIT?: No COORDINATED ATTACK: No. COMPLEX ATTACK: No COUNTER ATTACK: No MEDEVAC REQUESTED: No **BLOWN IN PLACE: No** SUMMARY: USF REPORT AT 14 0920 NOV 11, AN IED DETONATED ON A 2/B/2-8 CAV C-IED PATROL TRAVELING SOUTH ON MSR TAMPA. 2-8 CAV REPORTED NO CASUALTIES AND MINOR DAMAGE ORF AND EOD RESPONDED TO THE SITE TO CONDUCT PBA. (b)(1)1.4g (b)(1)1.4g WHEN PBA WAS COMPLETE ALL ELEMENTS RTB. AT APPROXIMATELY 1900, 1-1 AAB REPORTED THAT EOD ASSESSED THAT THE IED WAS AN EFP. EOD ASSESSMENT: ON 140935CNOV2011 752/1/3 MANEUVERED TO CONDUCT POST BLAST ANALYSIS ISO 2-8 CAV, BANDDOG GREEN 1 IVO 38S NA 01326 47260. EOD ARRIVED ON SITE, LINKED UP WITH ON-SCENE COMMANDER, CONDUCTED 5/25'S AND SET UP SAFE AREA. OSC STATED THAT WHILE TRAVELING SOUTH ON RTE TAMPA AN IED DETONATED ON THE WEST SIDE OF THE ROAD AND STRUCK THEIR LEAD VEHICLE. NO INJURIES TO PERSONNEL, VEHICLE RECEIVED RIGHT SIDE REAR DAMAGE TO (b)(1)1.4g FOD TEAM PERFORMED ARMORED RECONNAISSANCE OF THE SITE AND IDENTIFIED A LARGE BLAST SEAT APPROXIMATELY 2.5 METERS FROM THE ROAD NEAR A LARGE DIRT PILE. EOD TL DISMOUNTED AND PERFORMED RECONNAISSANCE OF THE AREA. TEAM TOOK PHOTOS AND MEASUREMENTS FROM THE SCENE, EOD TEAM LOCATED TWO SEPARATE IMPACT POINTS ON THE VEHICLE. (b)(1)1.4g CRATER MEASURES APPROXIMATELY 5FT X 6FT WITH A DEPTH OF 26 INCHES, NO EXPLOSIVE HAZARDS WERE

15-November-11 Page 2of 6

FOUND, EOD TEAM RTB.

#### SECRET//REL TO USA, FVEY

| TL ASSESSES  | TL ASSESSES (b)(1)1.4c, (b)(1)1.4g   |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|--|
| (b)(1)1.4c, (b)(1)1.4g                                   |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |
| 1-1 AAB S2 ASSESSMENT:                                   | (b)(1)1.4c   |  |  |  |  |  |  |  |
| (t   | (b)(1)1.4c   |  |  |  |  |  |  |  |
| EOD ASSESSED TODAY'S E                                   | VENT TO BE (b)(1)1.4c, (b)(1)1.4g  |  |  |  |  |  |  |  |
| THE DEVICE WAS MOST LIKELY HASTILY EMPLACED (NOT BURIED) |  |  |  |  |  |  |  |  |
| AND IN FRONT OF A SMALL DIRT MOUND BY A MOBILE           |  |  |  |  |  |  |  |  |
| EMPLACEMENT TEAM WH                                      | HEN NO USF OR ISF WERE PRESENT. WHILE  |  |  |  |  |  |  |  |
|  | AND BANDOG COMPANY WERE AT THE   |  |  |  |  |  |  |  |
|  | JNABLE TO IDENTIFY ANY COMMAND WIRE  |  |  |  |  |  |  |  |
| TYPE INITIATOR. WE ASSES                                 | The same of the sa |  |  |  |  |  |  |  |
|  | MED AND PIR INITIATED. WHILE IT IS ALSO  |  |  |  |  |  |  |  |
|  | ULD HAVE BEEN TOIR ARMED AND PIR   |  |  |  |  |  |  |  |
| INITIATED, WE DO NOT AS                                  | SSESS THIS TO BE THE CASE DUE T 16)(1)1.4c   |  |  |  |  |  |  |  |
|  | 200  |  |  |  |  |  |  |  |
|  | (b)(1)1.4c   |  |  |  |  |  |  |  |
| DUE TO THE TYPE OF DEVI                                  | ICE AND THE HISTORIC IED ACTIVITY IN THIS  |  |  |  |  |  |  |  |
|  | HIS ATTACK WAS CARRIED OUT BY (b)(1)1.4c   |  |  |  |  |  |  |  |
| AREA, WE ASSESS THAT TI                                  | III ATTACK WAS CARRIED OUT BY 10001130   |  |  |  |  |  |  |  |
| 1 1  |  |  |  |  |  |  |  |  |
| -0   |  |  |  |  |  |  |  |  |
| (0)  |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |
| .0   | (b)(1)1.4c   |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |
| O.   |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |
| (b)(1)1.4c PLANN   | NING RKG-3 AND IED ATTACKS ON U.S.   |  |  |  |  |  |  |  |
| FORCES AS THEY WITHDRAW FROM IRAQ. THE GROUP IS LED BY   |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |
| (b)(1)1.4c   |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |

USD-C G-2 ASSESSMENT: CONCURS WITH 1/1 CAV S2 ASSESSMENT



#### AND HAS NO FURTHER INFORMATION REGARDING THIS ATTACK.

#### BDA:

1 X VEHICLE DAMAGED (MINOR)

| ENEMY: |      | COALITION: |      |      |      |
|--------|------|------------|------|------|------|
| KIA:   | WIA: | DET:       | KIA: | WIA: | ABD: |
| 0      | 0    | 0          | 0    | 0    | 0    |

| CIVILIAN: |      | HOST NATION: |      |      |      |
|-----------|------|--------------|------|------|------|
| KIA:      | WIA: | ABD:         | KIA: | WIA: | ABD: |
| 0         | 0    | 0            | 0    | 0    | 0    |

#### **CCIR Status**

SUMMARY: USF-I DCG(O) IR 17: Any attack utilizing RKG-3, EFP, SVBIED and/or

**PBIED** 

**GROUP: USD-C G3 SIGACT MANAGER** 

#### **Capture Details**

#### **Casualty Details**

### Target(s) of Attack

PRECEDENCE: Primary TYPE: Coalition

AFFILIATION: Coalition SECT: Unknown

DETAILS: Other NATIONALITY: IRAQ

15-November-11 Page 4of 6

USCENTCOM FOIA 17-0112



STATUS: Unaffected

DESCRIPTION: Not Reported

#### **Indirect Fire Information**

# Vehicle/Convoy Details NUMBER OF VEHICLES: 0 DISTANCE BETWEEN VEHICLES: 0 Meters CONVOY SPEED: 0 MPH NEAREST ECM DIST TO IED: 0 Meters NEAREST ECM DIST TO VEHICLE STRUCK: 0 Meters OTHER COUNTERMEASURES ON VEHICLE STRUCK: Not Reported VEHICLE SUMMARY: Not Reported

| DRUGREP Details             |  |  |  |  |  |
|-----------------------------|--|--|--|--|--|
| FACILITY TYPE: Not Reported |  |  |  |  |  |
| Drugs Found                 |  |  |  |  |  |
|                             |  |  |  |  |  |
|                             |  |  |  |  |  |
| Chemicals Found             |  |  |  |  |  |
|                             |  |  |  |  |  |
|                             |  |  |  |  |  |
| Equipment Found             |  |  |  |  |  |

15-November-11 Page 5 of 6



| Reintegration Details      |                      |                      |                |  |  |  |
|----------------------------|----------------------|----------------------|----------------|--|--|--|
| REINTEGRATION OPEN:        |                      |                      | No             |  |  |  |
| REINTEGRATION OPEN COMMENT | ΓS:                  |                      | No             |  |  |  |
| NUMBER OF REINTEGRATEES:   |                      |                      | 9 0            |  |  |  |
|                            | FOLLOW UP DATES      | COMPLETED            | COMPLETED DATE |  |  |  |
| VETTING DATE:              | Not Reported         | No                   | Not Reported   |  |  |  |
| COMMUNITY TALK DATE:       | Not Reported         | No                   | Not Reported   |  |  |  |
| REINTEGRATION DATE:        | Not Reported         | No                   | Not Reported   |  |  |  |
| 7 DAY FOLLOW UP:           | <b>Not Reported</b>  | No                   | Not Reported   |  |  |  |
| 30 DAY FOLLOW UP:          | Not Reported         | No                   | Not Reported   |  |  |  |
| 60 DAY FOLLOW UP:          | Not Reported         | No                   | Not Reported   |  |  |  |
| 90 DAY FOLLOW UP:          | Not Reported         | No                   | Not Reported   |  |  |  |
| 180 DAY FOLLOW UP:         | Not Reported         | No                   | Not Reported   |  |  |  |
| REINTEGRATION CLOSED: No   | REINTEGRATION CLOSED | REASON: Not<br>Repor | ted            |  |  |  |
| REINTEGRATION CLOSED COMME | NTS:                 |                      | No             |  |  |  |

15-November-11 Page 6of 6

USCENTCOM FOIA 17-0112 084 08/08/2018



# (752ND / 1 / 3)

140925CNOV11

1/1 CAV SUPPORTED BCT

(b)(3), (b)(6)

<u>1</u>

<u>2-8 CAV BANDE</u>

**TEAM LEADER** 

ON SCENE COMM

38SNA0148046977 MGRS GRID LOCATION

MS TAM A

Sout DIRECTION OF

Blast
TYPE OF REPORT

EVENT CATEGORY

Othe METHOD OF EM

SIGACT #: 20111114092038SNA0132647260

**CIDNE #:** BLAST-20111114092538SNA0148046977

CCIR: DCG-O 12, 17 USD-C 18

|     | CF             | LN                | IA/IP/NP | E | U.S. Civilian | Coalition |
|-----|----------------|-------------------|----------|---|---------------|-----------|
| KIA | 0              | 0                 | 0        | 0 | 0             |           |
| WIA | O<br>USCENTCOM | O<br>FOIA 17-0112 | 0        | 0 | 0             | 085 0     |





USCENTCOM FOIA 17-0112

086 0



# Aerial / Map View of Site



## Time

**EOD Notification:** 

**EOD FOB Departure:** 

**EOD Scene Arrival:** 

**EOD Scene Departure:** 

**EOD Mission Complete:** 




USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU

087 0



# Scene Diagram



USCENTCOM FOIA 17-0112 088 0



# Narrative / Background

(UNCLASSIFIED // FOUO) On 140935CNOV2011 752/1/3 maneuvered to conduct Post Blast Analys 8 CAV, Banddog Green 1 IVO 38S NA 01326 47260. EOD arrived on site, linked up with On-Scene Commander, conducted 5/25's and set up safe area. OSC stated that while raveling south on RTE an IED detonated on the west side of the road and struck their lead vehicle. No injuries to person vehicle received right side rear damage to MEAP and body. EOD Team performed armored reconnaissance of the site and identified a large blast seat approximately 2.5 meters from the road large dirt pile at known grid. EOD TL dismounted and performed reconnaissance of the area. EOD took photos and measurements from the scene. EOD rea. located two segarate impact oints on vehicle, the impact area on the south approximately 10 inches in diameter with an estimated we 40lbs of UBE. Crater measures approximately 5ftx6ft with a depth of 26 inches. No explosive haza found. EOD Team RTB. MC: 141215CNOV11.

USCENTCOM FOIA 17-0112 089 0





# **EOD Team Leader Observations**

<u>InitiationType</u>

**Initiator** 

Main Charge

Container

Unknown

Unknown

Directional-EFP

Unknown

Improvised:

(UNCLASSIFIED // FOUO) TL assesses th (b)(1)1.4c, (b)(1)2 with approximately 40lbs of UBE.

(b)(1)1.4c, (b)(1)1.4g

USCENTCOM FOIA 17-0112 090 0



# Photographs of Scene



EAST FROM GRID 38S NA 01480 46977

USCENTCOM FOIA 17-0112



# Photographs of Scene



NORTH FROM GRID 38 S NA 01480 46977

USCENTCOM FOIA 17-0112



# Photographs of Scene



EAST FROM GRID 38S NA 01480 46977

USCENTCOM FOIA 17-0112 093 0



# Photographs of Scene




SOUTH FROM GRID 38S NA 01480 46977

USCENTCOM FOIA 17-0112 09



# Photographs of Scene



BLAST SEAT AT GRID 38S NA 01480 46977

USCENTCOM FOIA 17-0112



# Photographs of Scene



USCENTCOM FOIA 17-0112 096 0



# Photographs of Scene



(b)(1)1.4c, (b)(1)1.4g

USCENTCOM FOIA 17-0112 097 0



# Photographs of Scene



(b)(1)1.4c, (b)(1)1.4g

USCENTCOM FOIA 17-0112 098 0



# Photographs of Scene



(b)(1)1.4c, (b)(1)1.4g

USCENTCOM FOIA 17-0112 099 0



# Photographs of Scene



(b)(1)1.4g

USCENTCOM FOIA 17-0112 100 0



# Photographs of Scene



(b)(1)1.4g

USCENTCOM FOIA 17-0112 101 0



# Photographs of Scene



(b)(1)1.4g

USCENTCOM FOIA 17-0112 102 0



# Photographs of Scene



OTHER EFP IMPACT POINT WITH SCALE

USCENTCOM FOIA 17-0112 103 0



# Photographs of Scene



OTHER IMPACT AREA FROM EFP ON THE RIGHT SIDE REAR

(b)(1)1.4g

USCENTCOM FOIA 17-0112



# Photographs of Scene



SMALL FRAGMENTATION HOLE ON FRONT RIGHT SIDE

(b)(1)1.4g

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU

105 0



# Photographs of Scene



FRAGMENTATION HOLE IN

(b)(1)1.4g

WITH SCALE

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU

106 0